

3-phase stator ROT504 driven by dual speed rotor control unit

Measurements at the stator cable terminal EX1100 between 1-2 and 2-3 and 1-3

Inductances: Must all be 26mH $\pm 10\%$
Resistances: Must all be 12 Ohms $\pm 10\%$

cable resistance (10m single length) + 0.27 Ohms
(3 x 1.31mm²) (15m single length) + 0.40 Ohms
(20m single length) + 0.53 Ohms





